

FITNESS CERTIFICATE

1. Name of the School : Bharadwaja Vidya Pidam Central School - Parassala.
2. Name of the Officer : B.A. T.S. Clement.
3. Period for which the Certificate is issued : 2021 - 22
4. Classification of the building and size (basis for classification) (See annexure I) :
 - i) Permanent Single or multistoreyed :
 - ii) Semi permanent :
 - iii) Temporary shed :
5. Nature of defects if any
 - a) Foundation and basement :
 - b) Superstructure :
 - c) Doors and Windows :
 - d) Wood work wrought and put up :
 - e) Roof :
 - f) Flooring :
 - g) Miscellaneous (Craks etc.) :
6. Any major defects noticed which will render the building unsafe in any manner : No.
7. Whether maintenance works have been done properly : Yes
8. Whether the structure is sound or not for conducting classes : Sound under normal weather condition.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 29.07.2021
and found to be fit to conduct classes for the period 2021 - 22
for the reasons stated above.

Parassala,

Place: 29.7.2021

Date:

Signature :

Designation :

ASSISTANT ENGINEER
L.S.G.D. SECTION,
PARASSALA.

- I. $15.70 \times 8.30 \times 3.50$ G/F RCC Building.
 F/F " "
 II/F " Trafoled sheet -
 building.
- II. $61.80 \times 8.30 \times 3.50 \rightarrow$ G/F RCC Building.
- III. $66.5 \times 28.30 \times 3.60$
 - I/F RCC Building.
 - II/F " "
 - III Floor Trafoled sheet building
- IV. $23.05 \times 8.30 \times 3.50$. G/F RCC building.
- V. $34.65 \times 8.30 \times 3.50$
 - I & II floor RCC building.
 - III floor trafoled sheet -
building.
- VI. $12.00 \times 33.10 \times 3.50 \rightarrow$ Trafoled sheet building.




 ASSISTANT ENGINEER
 L.S.G.D. SECTION,
 PARASSALA.